

ABSTRACT OF THE DISCLOSURE

In a method for manufacturing a solid core of laminations, a sheet metal web is cut in the longitudinal direction of the sheet metal web to produce at least two sheet metal strips. The sheet metal strips are separated in a direction transverse to the longitudinal direction of the sheet metal strips to form laminations. The laminations are joined to form a solid core. Joining can be carried out by welding, riveting, gluing or pressing.

093694-0504
T05020 "4696860